SUBJECT: Carry-through Unit

 $41-390\frac{1}{2}$. LA-6 Models.

DATE: March 23, 1934

TO ALL OFFICES:


The camming surface of pawls 4307 and $4307\frac{1}{4}$ and aligner cams 4325,4326, 4327, 4328, 4329, 4330 and 4331, have been altered to provide better action when the carriage dials operate.

New style pawls 4307 and $4307\frac{1}{4}$ can be used with the old style aligner cams.

The new style aligner cams can not be used with the old style pawls.

The instructions given on Plates 7 and 8 of Machine Service Bulletin No. 178 should be followed in preference to installing the new style parts. However, if satisfactory results can not be obtained the new style material should be installed.

When requisitioning these parts identify the aligner cams by adding xl to their numbers and the check pawls by adding N. S.



SON AND REPORTED HOLVING THE PARTY AND A TONE Jan. Pro-Shapper St. W. W. AND DESCRIPTION OF THE PERSON Mr. B. P. James, Toledo. Ohio. The state of the second control of the secon · It we are in the other man man have been also altern file over with them an ann Armen har work to place a first and and many adopted from only of the selection of the contract of the selection of the selecti Manufacture must be the control of t The expense of the first temperature identifies the Education of the Committee of the Commi of the state of the contract of the form of the state of I was a line 18-206. marks in